

Contents

Preface	III
-------------------	-----

CHAPTER 1

Thermodynamics of Equilibria and Phase Diagrams	1
1.1 Course Reminders	1
1.1.1 Precipitation and Chemical Ordering	1
1.1.2 Thermodynamic Functions and Potentials	9
1.1.3 Binary Equilibria: Ideal and Regular Solid Solutions.	13
1.1.4 The Critical Transition Theory and the Landau Theory	19
1.2 Problems	23
1.2.1 Equilibrium Vacancy Concentration	23
1.2.2 Intergranular Segregation	27
1.2.3 Phase Diagrams and Regular Solution	32
1.2.4 Order–Disorder Transformations and Bragg–Williams Theory	40
1.2.5 Ordering in FCCs and Landau’s Theory	49
1.2.6 Ordering in BCCs and Landau’s Theory	55

CHAPTER 2

Diffusion and Transport in Solids	63
2.1 Course Reminders	63
2.1.1 Diffusion at the Atomic Scale	63
2.1.2 Fick’s Two Laws	68
2.1.3 Hetero-Diffusion, Kirkendall Effect	72
2.1.4 Diffusion Short Circuits: Influence of Defects	74
2.1.5 Driven Diffusion in a Force Field	75
2.2 Problems	78
2.2.1 Fundamental Mechanisms of Diffusion – Einstein’s Equation	78
2.2.2 Elementary Mechanisms and Self-Diffusion	82
2.2.3 Diffusion in CuAl Alloys	84
2.2.4 Surface Hardening by Cementation	89
2.2.5 Diffusion in Thin Sandwich Films	94
2.2.6 Kirkendall Effect and Diffusion in CuZn	100
2.2.7 Short-Circuits of Diffusion: Grain Boundaries and Dislocations	104

2.2.8	Driven Diffusion in a Force Field and Spinodal Decomposition .	108
2.2.9	A New Fick Law According to Howe	115
2.2.10	Driven Diffusion in a Force Field: Application to Nabarro-Herring Creep	122
2.2.11	Driven Diffusion of Impurities in a Force Field, the Formation of Cottrell Atmospheres	126
2.2.12	Diffusion in Semiconductors: The Generation of an Internal Nernst Field	132
2.2.13	Driven Diffusion in a Force Field: Oxidation of Nickel	139
CHAPTER 3		
	Kinetics of Formation of a New Phase	147
3.1	Course Reminder	147
3.1.1	Continuous and Discontinuous Precipitation	147
3.1.2	Instability and Metastability	150
3.1.3	Homogeneous Nucleation	154
3.1.4	Heterogeneous Nucleation	161
3.1.5	Nucleation of Metastable Phases	164
3.1.6	Growth	166
3.1.7	The Spinodal Decomposition	168
3.1.8	Coarsening	172
3.1.9	Overall Kinetics	175
3.2	Problems	177
3.2.1	Eutectoid Transformations	177
3.2.2	Nucleation of Precipitates in Ni-Al Alloys	185
3.2.3	Nucleation and Growth of Precipitates in Dilute Cu-Co Alloys	189
3.2.4	Heterogeneous Nucleation of Precipitates in AlCu	195
3.2.5	Deal and Grove's Growth Law of a Spherical Precipitate	200
3.2.6	Growth of an Oxide Film on Surface, Deal and Grove's law	205
3.2.7	Growth and Coarsening of Spherical Precipitates	211
3.2.8	Coarsening in NiAl Superalloys	220
3.2.9	Zener's Model for the Growth of a Precipitate with Incoherent Planar Interfaces	226
3.2.10	The Spinodal Decomposition	230
3.2.11	Zeldovich's Kinetic Theory of Nucleation and Incubation Time	238
3.2.12	Capture Coefficient, Nucleation Flux and Incubation Time	244
	References	255
	Index	257