

List of figures

- Figure 1** Graph between length of w/p and conicity — 2
- Figure 2** Graph between feed rate and center time average roughness — 6
- Figure 3** Graph between cutting speed and T_m — 7
- Figure 4** Graph between RPM and diameter of job — 9
- Figure 5** Graph between T.P.I. and gear ratio — 12
- Figure 6** Graph between diameter and RPM — 14
- Figure 7** Graph between facing length and machining time — 15
- Figure 8** Graph between shaping width and machining time — 17
- Figure 9** Graph between cutting time and machining time — 18
- Figure 10** Graph between peripheral speed and wheel speed — 19
- Figure 11** Graph between pin speed and machining time — 21
- Figure 12** Graph between RPM and drilling time — 22
- Figure 13** Graph between feed rate and machining time — 24
- Figure 14** Graph between rake angle and shear angle — 25
- Figure 15** Graph between chip thickness and shear angle — 27
- Figure 16** Graph between shear angle and force component — 28
- Figure 17** Graph between friction angle and force — 30
- Figure 18** Graph between feed rate and unit power — 31
- Figure 19** Graph between feed rate and force — 33
- Figure 20** Graph between RPM and power — 34
- Figure 21** Graph between SCEA and shear angle — 36
- Figure 22** Graph between depth and machining time — 38
- Figure 23** Graph between friction angle and contact length — 40
- Figure 24** Graph between feed rate and machining time — 41
- Figure 25** Graph between time and cutting speed — 43
- Figure 26** Graph between PCEA and change of temp. (%) — 44
- Figure 27** Graph between cutting angle and surface roughness — 45
- Figure 28** Graph between shear angle and orthogonal rake angle — 47
- Figure 29** Graph between side clearance angle and tool designate — 48
- Figure 30** Graph between axial rake angle for twist drill and helix angle — 49
- Figure 31** Graph between pitch and surface finish — 51
- Figure 32** Graph between shear angle and chip reduction coefficient — 52
- Figure 33** Graph between tool life and cutting velocity — 53
- Figure 34** Graph between cutting speed and machining time — 55
- Figure 35** Graph between cutting force and cutting velocity — 56
- Figure 36** Graph between crank radius and stroke length — 58
- Figure 37** Graph between cutting velocity and shear angle — 59
- Figure 38** Graph between gear blank speed and cutting velocity — 60
- Figure 39** Graph between cutting force and coefficient of friction — 61
- Figure 40** Graph between rake angle and coefficient of friction — 63
- Figure 41** Graph between depth of cut and machining time — 64
- Figure 42** Graph between idle time and machining time — 65
- Figure 43** Graph between orthogonal force component and depth of cut — 66
- Figure 44** Graph between surface roughness and shear angle — 68
- Figure 45** Graph between side rake angle and shear angle — 69
- Figure 46** Graph between inclination angle and shear angle — 72

- Figure 47** Graph between clearance angle and ORS — **73**
Figure 48 Graph between radial distance and axial rake angle — **74**
Figure 49 Graph between thread pitch and side rake angle — **75**
Figure 50 Graph between rake angle and cutting angle — **77**
Figure 51 Graph between average cutting temperature and ϕ — **78**
Figure 52 Graph between orthogonal rake angle and C_p — **79**
Figure 53 Graph between cutting velocity and power — **81**
Figure 54 Graph between cutting velocity and ratio — **82**
Figure 55 Graph between machining time and diameter — **83**
Figure 56 Graph between depth of cut and wheel speed — **85**
Figure 57 Graph between current and MRR — **86**