

List of tables

Table 1	Values of length of taper and conicity —	1
Table 2	Values of large diameter and conicity —	3
Table 3	Values of conicity and angle —	4
Table 4	Values of length and angle —	4
Table 5	Values of corner radius and feed rate —	5
Table 6	Values of cutting speed and T_m —	7
Table 7	Values of RPM and diameter of job —	8
Table 8	Values of pitch of the lead screw and gear ratio —	10
Table 9	Values of speed and gear ratio —	11
Table 10	Values of thread per inch (T.P.I.) and gear ratio —	12
Table 11	Values of diameter of workpiece and RPM —	13
Table 12	Values of facing length and machine time —	15
Table 13	Values of shaping width and machining time —	16
Table 14	Values of cutting ratio and machining time —	18
Table 15	Values of peripheral speed and wheel speed —	19
Table 16	Values of pin speed and machining time —	20
Table 17	Values of RPM and drilling time —	22
Table 18	Values of feed rate and machining time —	23
Table 19	Values of rake angle and shear angle and wheel speed —	25
Table 20	Values of chip thickness and shear angle —	26
Table 21	Values of shear angle and force components —	28
Table 22	Values of friction angle and force —	29
Table 23	Values of feed rate and unit power —	31
Table 24	Values of feed and force —	32
Table 25	Values of RPM and power —	34
Table 26	Values of side cutting edge angle and shear angle —	35
Table 27	Values of rake angle and temperature —	37
Table 28	Values of depth of cut and machining time —	38
Table 29	Values of friction angle and contact length —	39
Table 30	Values of wheel velocity and uncut thickness —	41
Table 31	Values of feed rate and machining time —	41
Table 32	Values of time and cutting speed —	42
Table 33	Values of PCEA and change of temperature —	44
Table 34	Values of cutting angle and surface roughness —	45
Table 35	Values of shear angle and orthogonal rake angle —	46
Table 36	Values of side clearance angle and tool designate —	48
Table 37	Values of axial rake angle for twist drill and helix angle —	49
Table 38	Values of pitch and surface finish —	50
Table 39	Values of shear angle and chip reduction coefficient —	52
Table 40	Values of tool life and cutting velocity —	53
Table 41	Values of cutting speed and machining time —	54
Table 42	Values of cutting force and cutting velocity —	56
Table 43	Values of crank radius and stroke length —	57
Table 44	Values of cutting velocity and shear angle —	59
Table 45	Values of gear blank and cutting velocity —	60
Table 46	Values of cutting force and coefficient of friction —	61
Table 47	Values of rake angle and coefficient of friction —	62

Table 48	Values of depth of cut and machining time —	64
Table 49	Values of idle time and machining time —	65
Table 50	Values of depth of cut and orthogonal force —	66
Table 51	Values of surface roughness and shear angle —	67
Table 52	Values of side rake angle and shear angle —	69
Table 53	Values of inclination angle and shear angle —	71
Table 54	Values of clearance angle and ORS —	73
Table 55	Values of radial distance and axial angle —	74
Table 56	Values of thread pitch and side rake angle —	75
Table 57	Values of rake angle and cutting angle —	76
Table 58	Values of average cutting temperature and $\varnothing$ —	78
Table 59	Values of orthogonal rake angle and C_p —	79
Table 60	Values of cutting velocity and power —	81
Table 61	Values of cutting velocity and ratio —	82
Table 62	Values of machining time and diameter —	83
Table 63	Values of depth of cut and wheel speed —	84
Table 64	Values of current and MRR —	86